
Metal Concentrations
10000
1000
100
10
1
Concentrations (ppm)
50
45
40
35
30
25
20
15
10
5
0
River Mile
Lead
Zinc
Copper
Chromium
Arsenic
Barium
PAHs