
Metal Concentrations
Concentration (ppm)
800
700
600
500
400
300
200
100
0
-100
50
40
30
20
10
0
River Mile
Barium
Chromium
Copper
Arsenic


0