

1 NEW MARTINSVILLE HIGHWAY BRIDGE

A MARTIN MARIETTA AGGREGATES
B ARROW CONCRETE
C DOCK SIDE INC.
D HARMAN'S HARBOR

NOTE
When the river level is above the Ordinary High Water elevation all navigators are urged to sail near the sailing line to prevent bank erosion.

NOTE: SEE OPPOSITE PAGE FOR CLEARANCE DATA.

OHIO RIVER

500' 0 500' 1500'

SCALE 1"=1500'
REVISED: 1999

CHART NO. 173