



**US Army Corps
of Engineers®**

PITTSBURGH DISTRICT

ATTN: CELRP-DE - ROOM 2032
1000 LIBERTY AVENUE
PITTSBURGH PA 15222-4186
HTTP://WWW.LRP.USACE.ARMY.MIL/

NAVIGATION NOTICE

DATE:

POC: Jason Prince
Operations
Division
(412) 395-7241

NOTICE NUMBER: 712-1

LOCAL NUMBER: 14-12
WATERWAY: ALLEGHENY RIVER

EFFECTIVE: 06/22/2015 00:01 thru Until Further Notice
EST

C.W. Bill Young L/D, Allegheny River, Mile 14.5
Missing Wall Armor

UPDATE: In addition there is an 8-ft section of wall armor missing on the land wall at the 25-ft mark. There is currently no impacts to navigation.

- 1. TO ALL WHOM IT MAY CONCERN:** Notice is given that a 20-ft section of wall armor is missing on the landwall at C.W. Bill Young L/D, Allegheny River. This missing section is located on the land wall at the 125-ft mark of the lock chamber.
2. Navigators are urged to use caution while traversing this area and make every effort not to rub against the landwall while locking through the chamber. This could result in adjacent sections being dislodged.
3. Commercial navigators shall use extreme caution while locking through the chamber. A flat edge exists on either side of the missing wall armor which can easily be hit causing damage to the wall armor or their vessel. In order to identify the missing section, both ends have been sprayed with highly visible orange spray paint.
4. Recreational vessels will **NOT** be moored adjacent to this area.
5. A revised Navigation Notice will be issued once the repairs have been made.

FOR THE DISTRICT ENGINEER :

//signed//

Richard C. Lockwood
Chief, Operations and Regulatory Division