



**US Army Corps
of Engineers®**

PITTSBURGH DISTRICT
ATTN: CELRP-DE - ROOM 2032
1000 LIBERTY AVENUE
PITTSBURGH PA 15222-4186
HTTP://WWW.LRP.USACE.ARMY.MIL/

NOTICE TO NAVIGATION INTERESTS

DATE: 03/07/2016
POC: Jason Prince
Operations Division
412-395-7241

NOTICE NUMBER: 5995
LOCAL NUMBER:
WATERWAY: OHIO RIVER

EFFECTIVE: 03/14/2016 07:00 thru 04/01/2016 23:59 EST

Ohio River Mile 31.7, Montgomery Locks and Dam, Repairs to Auxiliary Chamber Lower Sill

1. **To All Whom It May Concern:** Notice is given that the U.S. Army Corps of Engineers' Repair Fleet will be making repairs to the 56-ft x 360-ft river lock chamber at Montgomery L/D, Ohio River. The work includes repairs to the lower river lock chamber sill.
2. During the repair work at Montgomery, all mariners are urged to use extreme caution when approaching and exiting the primary chamber. The Repair Fleet will be moored in the lower auxiliary chamber approach, and divers will be working between the hours of 7:00am and 12:00am daily.

FOR THE DISTRICT ENGINEER:

//signed//

Kathy M. Griffin
Chief Operations and Regulatory Division