


Figure 3- 2. Lower Mahoning River Ohio and PA, Stream Channel Sediment Quality Metal Analyses, 1998 and 2000



Ohio samples were composited 0 to 4 feet deep;
 Pennsylvania samples were 0 to 6 inches or surface