



X Dashed box refers to remedial alternatives that are not recommended.

FIGURE 16
REMEDIAL ALTERNATIVES FOR
CONTAMINATED SEDIMENTS
 MAHONING RIVER ENVIRONMENTAL
 DREDGING RECONNAISSANCE STUDY
 TRUMBULL AND MAHONING COUNTIES, OHIO